
FORM MR-AR (Revised 3/98)

STATE OF UTAH DEPARTMENT OF NATURAL RESOURCES DIVISION OF OIL, GAS AND MINING

1594 West North Temple - Suite 1210 Box 145801 Salt Lake City, Utah 84114-5801 Telephone: (801) 538-5291

Fax: (801) 359-3940



ANNUAL REPORT OF MINING OPERATIONS

The informational requirements of this form are based on provisions of the Mined Land Reclamation Act, Title 40-8, Utah Code Annotated 1953, as amended, and the General Rules as promulgated under the Utah Minerals Regulatory Program. An operator conducting mining operations under a Notice of Intention must file an annual operations and progress report (FORM MR-AR) with the Division.

I.	<u>Gene</u>	<u>eral Information</u>		
	1. Report Time Period: From (mo./yr.) 1 99 To (mo./yr.) 1 2000			
	2.	DOGM File Number (Mine No): M /030/025		
	3.	Mine Name: LYNN SPRING QUARRY		
	4.	Mineral(s) Mined (or permitted to mine): MICACEOUS QUARTZITE SCHIST		
	5.	Type of mine ☐ Surface Mine or ☐ Underground Mine		
	6.	Legal Description (Location of Lands Affected):		
		1/4, W 1/2, NE 1/4, Section 29, Township [4N], Range 16 W		
		1/4,1/4,1/4, Section, Township, Range		
		1/4,1/4,1/4, Section, Township, Range		
7.	7. Name of Operator or Company: UTAH BUILDING STONE SUPPLY			
	8.	Permanent Street Address: 842 WEST 400 NORTH		
		City, State, Zip: WEST BOUNTIFUL, UTAH 84087		
		Phone: 801-295-0601 Fax: 801-295-0601		
	9.	Company Representative (or designated operator):		
		Name: WILLIAM BOWN		
		Title: OWNER		
		Business Address: SAME AS I.8		
		City, State, Zip:		
		Phone: Fax:		
		☐ Please check if any of the above information has changed since previous year.		
TT	Mini	us and Declaration		
II.	Mini	ng and Reclamation		
	1. Was there any mine related activity during the past year? Yes ☑ No ☐			
	2.	If no - what was the last year of activity?		
	3.	2.		
	_			

4.	Briefly describe the type of work perf additional surface disturbances that of	Formed, volume of material moved, and any new or ecurred during the past year.	
5.	How much additional acreage was disturbed during the past year? How much acreage was reclaimed during the past year?		
6.			
7.		amation work performed during the past year. This description employed, and an evaluation of the results.	
 What is the <u>total</u> disturbed acreage of entire project at years end? Briefly summarize any mining and/or reclamation plans for the upcoming year 			
NOTE:	Section III., "Additional Information"	applies only to <u>large mining operations</u> .	
III. <u>Additional</u>	<u>Information</u>		
1.	An updated surface facilities map should be attached if there have been significant changes since the previous map was submitted.		
2.	2. Any monitoring results or other reports that are required under the terms of the approved notice intention should also be attached.		
IV. Signature	<u>Requirement</u>		
I here	eby certify that the foregoing is tru	e and correct.	
	Name (Typed or Print):	WILLIAM L BOWN	
	Title of Operator:	OWNER	
	Signature of Operator:	William & Bow	
	Date:	1-22.00	
jb a:\forms\MR-AR		·	

- 2 -

Annual Quarry Report

Lynn Spring Quarry

Item #4

Work performed during the past year included continued excavating of the quarry deposit, removal of bulk material to processing area, processing and removal to Park Valley. It is estimated that 500 tons of material was displaced. 454 tons were produced, leaving roughly 50 tons of waste rock. This rock was replaced in the quarry, or lies at the processing area. There was no new surface disturbance during the past year.

Item #5

No new or additional surface disturbance.

Item #6,7

During the past year there was no new reclamation performed.

Item #8

Total acreage disturbance is not known

Item #9

Operations will continue during the upcoming year much as last year. There may be the introduction of a stone splitting machine to this operation. Exhaustive tests have shown that this particular material is capable of being "snap-cut" into pre-determined shapes. Most materials of this general nature will shatter when an attempt to snap-cut them is made. However, the material from the Lynn Spring Quarry is quite reliable as snap stock.